


To: Schmittiel, Paula[Schmittiel.Paula@epa.gov]
From: Peterson, Cynthia
Sent: Fri 5/22/2015 7:00:24 PM
Subject: RE: Photo captions



Thanks for getting these together!

Cynthia Peterson
Community Involvement Coordinator
Public Affairs and Community Involvement
U.S. Environmental Protection Agency, Region VIII
1595 Wynkoop St. (8OC-PAI)
Denver, CO 80202-1129
303-312-6879 -- direct dial

From: Schmittiel, Paula
Sent: Friday, May 22, 2015 11:41 AM
To: Peterson, Cynthia
Subject: Photo captions

I just realized that I sent these from my i-Pad and forgot to label them. I'll list them here in order of email and in order of appearance in email. Sorry about that.

1st email: 1. Looking down on the Animas river flood plain by Eureka townsite from

road up Eureka Gulch

2. Same thing – just slightly different angle.
3. Columbia Mine (?) –at Animas Forks
4. At Animas Forks area

2nd email: 1. Pretty view near Animas Forks
townsite 2. Old Sunnyside Mill (or is the name May Flower Mill??) above Eureka
Howardsville 3. Kittmack Tailings along the Animas River between Eureka and

3rd email: 1. Looking at May Flower Mill with capped tailings to left of mill and river with mineralized outcropping in foreground
2. Red & Bonita mine with discharge flowing down front face – some of the white is aluminum that has crusted over.
3. Alluvial wetlands adjacent to Cement Creek that has been destroyed by the discharge from the R/B.
4. Another view point of destroyed wetlands with discharge pipe at right foreground.

4th email: 1. Gold King Mine
2. Discharge from Gold King Mine
3. Same as #2

5th email: 1. Animas River below Silverton in the canyon – notice the red staining of rocks at edge of river.

Paula Schmittiel

Remedial Project Manager

U.S. Environmental Protection Agency

1595 Wynkoop St.

Denver, CO 80202

Office: 303-312-6861

Fax: 303-312-7151

Cell: 720-951-0795